

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	106937	((shock support post strut) same (fluid hydraulic) near4 (piston cylinder))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/07/31 16:02
L2	18695	1 and ((belt sling strap band hammock cradle) same (shock support post strut))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/07/31 16:15
L3	1886	2 and ((belt sling strap band hammock cradle) near4 (shock support post strut) same ((shock support post strut) same (fluid hydraulic) near4 (piston cylinder)))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/07/31 16:17
L4	918	3 and ((piston cylinder strut shock) same (level\$4 rocking rolling self-level\$4 swaying swinging upright\$4))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/07/31 16:21
L5	921	3 and ((piston cylinder strut shock) same (overpressure level\$4 rocking rolling self-level\$4 swaying swinging upright\$4))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/07/31 17:38

EAST Search History

L6	89	<p>(US-20040037646-\$ or US-20050156407-\$ or US-20030161708-\$ or US-20010006590-\$ or US-20040089212-\$).did. or (US-4732102-\$ or US-4029227-\$ or US-6457904-\$ or US-3539065-\$ or US-4480714-\$ or US-3409153-\$ or US-3540610-\$ or US-D526932-\$ or US-6390762-\$ or US-4232879-\$ or US-5114168-\$ or US-4880124-\$ or US-4538952-\$ or US-3688932-\$ or US-4468150-\$ or US-5655733-\$ or US-2657934-\$ or US-2667984-\$ or US-3640413-\$ or US-3045839-\$ or US-4049143-\$ or US-6612601-\$ or US-RE36971-\$ or US-4219094-\$ or US-3251433-\$ or US-5180070-\$). did. or (US-4699558-\$ or US-4279565-\$ or US-5056981-\$ or US-4861218-\$ or US-4236859-\$ or US-6257167-\$ or US-3356239-\$ or US-4522548-\$ or US-3622025-\$ or US-5037237-\$ or US-RE25276-\$ or US-3957165-\$ or US-2896803-\$ or US-3688931-\$ or US-4213728-\$ or US-4649581-\$ or US-6408778-\$ or US-6540245-\$ or US-4915577-\$ or US-3329284-\$ or US-6485247-\$ or US-4913614-\$ or US-4889465-\$ or US-2889061-\$ or US-5575607-\$ or US-3181717-\$ or US-3083850-\$). did. or (US-3572743-\$ or US-2853308-\$ or US-4440265-\$ or US-4195948-\$).did. or (US-3356239-\$ or US-3521773-\$ or US-3251433-\$ or US-3409153-\$ or US-3442409-\$ or US-2889061-\$ or US-2896803-\$ or US-RE25276-\$ or US-3181717-\$ or US-3329284-\$ or US-3045839-\$ or US-3468440-\$ or US-3192722-\$ or US-3177668-\$ or US-2603369-\$).did. or (WO-9954165-\$ or EP-566545-\$ or DE-4109578-\$ or WO-3089268-\$). did. or (SE-9100808-\$ or WO-2003089268-\$ or SE-9701222-\$ or SE-9701221-\$ or SE-9300764-\$ or WO-9954165-\$ or SE-501759-\$ or WO-200168444-\$).did.</p>	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2007/07/31 17:38
----	----	--	--	----	----	------------------

EAST Search History

L7	27	6 and ((piston cylinder strut shock) same (overpressure level\$4 rocking rolling self-level\$4 swaying swinging upright\$4))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/07/31 17:39
L8	3	7 and (overpressure)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/07/31 17:40

EAST Search History

S29	83	(US-20040037646-\$ or US-20050156407-\$ or US-20030161708-\$ or US-20010006590-\$).did. or (US-4732102-\$ or US-4029227-\$ or US-6457904-\$ or US-3539065-\$ or US-4480714-\$ or US-3409153-\$ or US-3540610-\$ or US-D526932-\$ or US-6390762-\$ or US-4232879-\$ or US-5114168-\$ or US-4880124-\$ or US-4538952-\$ or US-3688932-\$ or US-4468150-\$ or US-5655733-\$ or US-2657934-\$ or US-2667984-\$ or US-3640413-\$ or US-3045839-\$ or US-4049143-\$ or US-6612601-\$ or US-RE36971-\$ or US-4219094-\$ or US-3251433-\$ or US-5180070-\$). did. or (US-4699558-\$ or US-4279565-\$ or US-5056981-\$ or US-4861218-\$ or US-4236859-\$ or US-6257167-\$ or US-3356239-\$ or US-4522548-\$ or US-3622025-\$ or US-5037237-\$ or US-RE25276-\$ or US-3957165-\$ or US-2896803-\$ or US-3688931-\$ or US-4213728-\$ or US-4649581-\$ or US-6408778-\$ or US-6540245-\$ or US-4915577-\$ or US-3329284-\$ or US-6485247-\$ or US-4913614-\$ or US-4889465-\$ or US-2889061-\$ or US-5575607-\$ or US-3181717-\$ or US-3083850-\$). did. or (US-3572743-\$ or US-2853308-\$).did. or (US-3356239-\$ or US-3521773-\$ or US-3251433-\$ or US-3409153-\$ or US-3442409-\$ or US-2889061-\$ or US-2896803-\$ or US-RE25276-\$ or US-3181717-\$ or US-3329284-\$ or US-3045839-\$ or US-3468440-\$). did. or (WO-9954165-\$ or EP-566545-\$ or DE-4109578-\$ or WO-3089268-\$).did. or (SE-9100808-\$ or WO-2003089268-\$ or SE-9701222-\$ or SE-9701221-\$ or SE-9300764-\$ or WO-9954165-\$ or SE-501759-\$ or WO-200168444-\$).did.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2007/07/31 12:44
S30	24	S29 and ((shock support post strut) same (fluid hydraulic) near4 (piston cylinder))	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	ON	2007/07/31 16:01